



Photo 1 – View of Main Wreckage as Found (Lycoming)



Photo 2 – View of Engine as Found (Lycoming)



Photo 3 – View of Engine During Recovery (Lycoming)



Photo 4 – View of Propeller as Found (Lycoming)



Photo 5 – View of Angularly Cut Wood at Accident Site (Lycoming)



Photo 6 – View of Wreckage Layout at Recovery Facility (Piper)