



Photo 1 – NTSB Digital Photograph. Left Side View of the Inverted Airplane at the Accident Site.



Photo 2 – NTSB Digital Photograph. Forward View of the Inverted Airplane at the Accident Site. Note the damage to the Leading Edge's of Both Wings.



Photo 3 - NTSB Digital Photograph. Close-Up View of the Right Wing and Right Side of the Inverted Airplane at the Accident Site. Note the Damage to the Leading Edge of the Right Wing.



Photo 4 - NTSB Digital Photograph. Close-Up View of the Separated Engine Assembly behind Left Wing of Inverted Airplane at the Accident Site.



Photo 5 - NTSB Digital Photograph. View of the Airplane at the Accident Site Following Being Uprighted. Note the damage to the Leading Edge's of Both Wings.



Photo 6 - NTSB Digital Photograph. View taken from the Initial Ground Impact Looking to the East Depicting the Impacted Tree to the Right. Note the Angle of the Cut Limbs/Branches.



Photo 7 – Drone Image Provided by Doug Clark. View Looking to the Northwest Depicting the Cut and Broken Tree Branches/Limbs.



Photo 8 - Drone Image Provided by Doug Clark. View Depicting the Initial Impact Crater, Ground Scar, and Inverted Airplane at the Accident Site.



Photo 9 - NTSB Digital Photograph. View of the Propeller Assembly and Reduction Gearbox. Only 1 Propeller Blade remained Secured.



Photo 10 – Hartzell Digital Photograph. View of the Propeller Blades After Cleaning. Note the Varying Amount of Bending.