



Photo 1 – Aerial view of the wreckage. (Photo courtesy of the Civil Air Patrol)



Photo 2 – Initial tree strike and fragments of airframe.



Photo 3 – Tree branch cut at a 45° angle.



Photo 4 - Beginning of the wreckage path, looking forward towards the engine.



Photo 5 – View of the fuselage, the engine in the background.



Photo 6 – Main section of the engine.



Photo 7 – View of the wreckage path from the engine looking back.