



Photo 1 – Overview of Accident Site



Photo 2 – View of Rudder



Photo 3 – View of Main Wing Spar



Photo 4 – View of Right Engine



Photo 5 – View of Left Engine



Photo 6 – View of Standby Attitude Indicator