



Photo 1 – Aft view of wreckage showing damaged vertical and horizontal stabilizers



Photo 2 – Right-side view of wreckage showing damaged right wing and crushed cockpit



Photo 3 – Left-side view of wreckage showing damaged left wing



Photo 4 – Front view of wreckage showing the crushed cockpit



Photo 5 – Forward view of wreckage showing fragmented cockpit parts and instrument panel



Photo 6 – View of damaged instrument panel within the debris path