



Photo 1 – Debris Path



Photo 2 – Main Wreckage



Photo 3 – Left Propeller Blade



Photo 4 – Right Propeller



Photo 5 – Cut Branch With Black Paint Transfer



Photo 6 – Gyro Housing