



Photo 1 – View of Main Wreckage as Found (FAA)



Photo 2 – View of Left Wing Leading Edge as Found (FAA)



Photo 3 – View of Engine after Recovery (Lycoming)



Photo 4 – View of Flap Actuator as Found (FAA)



Photo 5 – View of Angular Cut to Fractured Tree Trunk at Site (FAA)



Photo 6 – View of Angularly Cut Tree Trunk Sections at Site (FAA)