



Photo 1 – Front view of wreckage of airplane



Photo 2 – View of the damaged right side of the empennage



Photo 3 – View of banner tow rope entangled right horizontal stabilizer



Photo 4 – View of damaged vertical and horizontal stabilizer



Photo 5 – View of left wing showing damage



Photo 6 – View of inboard section of right wing



Photo 7 – View of damaged outboard right wing