



Photo 1 – Wreckage in the water before recovery.



Photo 2 –Wreckage on recovery barge.



Photo 3 – Close up of left wing damage.



Photo 4 – Close up of damage to wing structure. Note the wing is upside down to facilitate examination. The left side of the photograph is the right wing.



Photo 5 – View of left wing and strut damage.



Photo 6 – Overall view of fuselage, right float and wing in background.