



Photo 1 – FAA Digital Photograph. Left Side View of the Airplane at the Accident Site.



Photo 2 - FAA Digital Photograph. Rear View of the Airplane at the Accident Site.



Photo 3 – Textron Aviation Photograph. Left Forward Quartering View of the Airplane Following Recovery.



Photo 4 - Textron Aviation Photograph. Right Rear Quartering View of the Airplane Following Recovery.



Photo 5 - Textron Aviation Photograph. Close-Up Right Rear Quartering View of the Inboard Section of Right Wing and Section of Fuselage. Note the damage to the wing.



Photo 6 - Textron Aviation Photograph. View of the Instrument Panel.



Photo 7 - Textron Aviation Photograph. View of the Instrument Panel Depicting the Avionics Master Switch.



Photo 8 - Textron Aviation Photograph. Front View of the Airplane Following Recovery. Note the Propeller Blade Damage.




Photo 9 - Textron Aviation Photograph. View of the Co-Pilot Side Lower Instrument Panel.




Photo 10 - Textron Aviation Photograph. View of the Arcing damage to the Electrical Wire of the Avionics Master Switch and the Aft Portion of the Adjacent Autopilot Control Unit.