



**Photo 1 – Profile View of Gyrocopter (Courtesy of FAA)**



**Photo 2 – View of Damage to Landing Gear Strut (Courtesy of FAA)**



**Photo 3 – View of Compression Damage to Engine Control Quadrant (Courtesy of FAA)**



**Photo 4 – View of Damage to Airframe Aft of Engine Compartment (Courtesy of FAA)**