



Photo 1 – Main Wreckage (FAA Photo)



Photo 2 – Left Engine and Propeller (FAA Photo)



Photo 3 – Fire/Heat Discoloration of Left Engine Nacelle Louvers



Photo 4 – Discoloration on Left Engine Components (FAA Photo)