



Photo 1 – Photo of fuel and oil slick



Photo 2 – Photo of various floating debris and fuel oil slick



Photo 3 – View of recovered outer side of crush damage pilot's side door



Photo 4 – View of inner side of recovered crush damaged pilot's door



Photo 5 – View of recovered outer side of crush damaged passenger door



Photo 6 – View of inside of crush damage passenger door



Photo 7 – View of recovered seatback cushion



Photo 8 – View of recovered small part of leading edge of wing showing crush damage



Photo 9 – View of recovered various fuselage skin pieces all showing crush damage



Photo 10 -View of recovered nose gear wheel attached to broken strut



Photo 11 – View of recovered main landing gear wheel