



Photo 1 – View of fuselage showing crush damage



Photo 2 – View of separated empennage with buckling and crush damage on horizontal stabilizer