

RECORD OF ☒ VISIT ☐ CONFERENCE OR ☐ TELEPHONE CALL		TIME 8:00 PM	DATE 06/10/2018
NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION PIC Enrique Gutierrez, PIC N3889D, ASI Jayson Arzuaga, ASI Rafael C.		ROUTING	
		SYMBOL	INITIALS
Gonzalez			
Centro Medico Hospital, San Juan, Puerto Rico			
SUBJECT N3889D Crash			
DIGEST			
Mr. Gutierrez stated that aircraft N3889D departed from runway 8 in Antonio Juarbe Pol			
Airport (ABO) in Arecibo, Puerto Rico, after rotation aircraft gain altitude and turn left			
heading north climbing to 275ft, immediately aircraft started to vibrate and a loud			
clicking sound was heard coming from the engine, the PIC then turn left heading west to			
return to the airport but engine quit after 3 seconds, Mr. Gutierrez shut off the fuel			
supply, used full flaps and touch down at 60 knots on a grassy field north of runway 8. As			
soon as the nose landing gear touch the ground, the front of the aircraft collapsed			
flipping the aircraft upside-down. When asked why he was so low in altitude the PIC claimed			
he was mitigating traffic (parachute-jumpers with open canopy) coming from the east			
belonging to Xtreme Divers.			
When we asked if he had engine problems the day before, the PIC answered no, that the			
engine was running rough back in January but after maintenance, the engine was running			
smoothly. During the interview he mention that he was in a lot of pain due to a broken			
Pelvis, we decided to cut the interview short for a later day.			
CONCLUSION, ACTION TAKEN, OR REQUIRED			
Interview rescheduled for a later day.			
DATE 06/10/2018	TITLE ASI	SIGNATURE 	

RECORD OF ☒ VISIT ☐ CONFERENCE OR ☐ TELEPHONE CALL		TIME 3:10 PM	DATE 06/10/2018
NAME(S) OF PERSON(S) CONTACTED OR IN CONFERENCE AND LOCATION Ramon Diaz Sambrana, Skydive Puerto Rico Diving Instructor, ASI Jayson		ROUTING	
		SYMBOL	INITIALS
Arzuaga, ASI Rafael C. Gonzalez			
Pavia Hospital, Arecibo Puerto Rico			
SUBJECT N3889D Crash			
DIGEST			
Mr. Diaz stated that aircraft N3889D departed from runway 8 in Antonio Juarbe Pol Airport (ABO) in Arecibo, Puerto Rico, after rotation aircraft gain altitude and turn left heading north when aircraft started to vibrate and a loud clicking sound was heard coming from the engine, PIC informed the passengers of the emergency.			
Mr. Diaz did not smelled fuel or smoke and does not remember if the engine quit before impact.			
CONCLUSION, ACTION TAKEN, OR REQUIRED			
DATE 06/10/2018	TITLE ASI	SIGNATURE 	

RECORD OF ☐ VISIT ☐ CONFERENCE OR ☒ TELEPHONE CALL		TIME 4:20 PM	DATE 06/21/2018
NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION Timothy Sheehan, Skydive Puerto Rico Diving Instructor, ASI Jayson Arzuaga,		ROUTING	
		SYMBOL	INITIALS
ASI Rafael C. Gonzalez			
SJU FSDO-63			
SUBJECT N3889D Crash			
DIGEST			
Mr. Sheehan stated that aircraft N3889D departed from runway 8 in Antonio Juarbe Pol			
Airport (ABO) in Arecibo, Puerto Rico, after rotation aircraft gain altitude but remained			
very low for what normally he experience as a diving instructor, then the PIC turn left			
heading north when aircraft started to vibrate and a loud clicking sound was heard coming			
from the engine, PIC informed the passengers of the emergency.			
Mr. Sheehan did not smelled fuel or smoke and was sure the engine quit but he does not			
recalled the emergency landing, the next thing he remember was somebody putting a needle in			
his arm in the hospital.			
CONCLUSION, ACTION TAKEN, OR REQUIRED			
DATE 06/21/2018	TITLE ASI	SIGNATURE 	