



Photo 1 – Airplane Wreckage (Photo Credit: FAA)



Photo 2 – Hole in Engine Cowling and Oil Residue (Photo Credit: FAA)



Photo 3 – Hole in Left Side Engine Cowling (Photo Credit: FAA)



Photo 4 – No. 2 Cylinder Separated from Engine (Photo Credit: FAA)




Photo 5 – No. 2 Cylinder Mounting Deck (Photo Credit: FAA)



Photo 6 – Broken Sections of Crank Case in Lower Engine Cowling (Photo Credit: FAA)