



Photo 1 – Main Wreckage, Front view



Photo 2 – Tail number



Photo 3 – Fractured roller tappet



Photo 4 – exemplar roller tappet