



Photo 1 – FAA Digital Photograph. Frontal View of the Inverted Wreckage at the Accident Site.



Photo 2 - FAA Digital Photograph. Left Forward Quartering View of the Inverted Wreckage at the Accident Site.



Photo 3 - FAA Digital Photograph. Right Forward Quartering View of the Inverted Wreckage at the Accident Site.



Photo 4 - FAA Digital Photograph. View of the Throttle Quadrant and Portion of Instrument Panel.



Photo 5 - FAA Digital Photograph. View of the Fuel Selector Valve in the Right Main Tank Position.



Photo 6 – Continental Aerospace Technologies Digital Photograph. View During Operational Testing of the Engine in the Test Cell.