



Photo 1 – View of Crash Site Facing Direction of Travel (Sebring FD)



Photo 2 – View of Main Rotor Head, Blades, and Pylon



Photo 3 – View of Engine, Propeller Gearbox, and Propeller Hub



Photo 4 – View of Initial Ground Scar




Photo 5 – View of Upper Flight Controls (AutoGyro USA)



Photo 6 – View of Roll Cable, Sheath, Roll Control Clevis (AutoGyro USA)



Photo 7 – View of Pitch Control Cable, Sheath, Rod-End Clevis, and Control Tube Pitch Horn (AutoGyro USA)



Photo 8 - View of Pitch Control Cable, Sheath, Rod-End Clevis, and Control Tube Pitch Horn (AutoGyro USA)