



Photo 1 – View of the severed power lines.



Photo 2 – Right side view of the wreckage.



Photo 3 – View of the separated tail boom.



Photo 4 – View of the instrument panel.