



Memorandum For Record

Timothy W. Monville
Sr. Air Safety Investigator
Eastern Region

Date: July 27, 2020
NTSB Accident Number: ERA19FA060

A 37-second video clip taken by an employee (Corey Matthews) of EA Management Services depicting a portion of the airplane during departure was provided to NTSB for review. The individual was located on the east and north ends of the Fort Lauderdale Executive Airport. The video depicted the accident airplane when it was west of the individual flying wings level with the landing gear retracted. The airplane went out of view briefly, came back into view when it was east of the individual, then briefly went out of view. As the airplane continued in an easterly direction the individual zoomed in and about 34 seconds elapsed time, smoke is noted trailing the airplane. The airplane was observed in a shallow left bank with smoke continuing to trail the airplane, then about 36 seconds elapsed time, the video panned to the ground and about 1 second later did not record any further video or audio.

The video was provided to the NTSB Fire and Explosion expert.

A 1 minute 20 seconds long video clip titled IMG_0466.MOV that captured the building impact and a few seconds before was provided by a tenant of a nearby building. The camera was facing a westerly direction, and depicted the left side of the airplane. NTSB review of the provided video clip revealed the outer portion of the right wing first came into view behind a vehicle. The airplane continued sliding on the ground in a southerly direction and the outer portion of the left wing was curled up nearly 180° with white colored mist trailing the airplane. Close inspection of the upper portion of the left engine cowling revealed an access door appeared to be open while the airplane was sliding on the ground. The airplane impacted the building and a fireball occurred. A three second gap in recorded time was noted. The video depicted occupants exiting the impacted building and personnel running towards the building to render assistance.

The video was provided to the NTSB Fire and Explosion expert.