



Photo 1 – View of Main Wreckage as Found



Photo 2 – View of Main Wreckage as Found Facing Direction of Downwind Leg of Traffic Pattern.



Photo 3 – View of Lexan, PVC, and Zip-Tie Cockpit Enclosure Fragments



Photo 4 – View of Propeller Blade



Photo 5 – View of BRS Cable Wrapped around Propeller Hub



Photo 6 – View of PVC-Tubing Frame for Cockpit Enclosure Secured with Zip-Ties




Photo 7 – View of Lexan Scrap on Pilot/Owner’s Hangar Floor



Photo 8 - View of Zip-Tie Scrap on Pilot/Owner's Hangar Floor