



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

October 3, 2019

STRUCTURES

Group Chairman's Factual Report

ERA19FA068

**Appendix A – Figures
(3 pages)**




Figure 1 – Azalea Saberwing airplane



Figure 2 – Azalea Saberwing accident airplane, N203SW



Figure 3 – Left longeron fracture, forward fuselage section



Figure 4 – Right longeron fracture, forward fuselage section



Figure 5 – Right center wing forward spar, looking aft



Figure 6 – Left outboard wing forward spar attachment