



Photo 1 –Overview of Accident Site



Photo 2 – View of Empennage at Accident Site



Photo 3 – View of initial tree strike (Courtesy of Textron Aviation)



Photo 4 – Overview of wreckage (Courtesy of Salvage Company)




Photo 5 – View of Gyroscopic Scoring from Standby Attitude Indicator




Photo 6 – View of gyroscopic scoring from primary attitude indicator housing