



Photo 1 – Aircraft Wreckage as Found (Textron)



Photo 2 – Aircraft Wreckage During Recovery (Textron)



Photo 3 – View of Engine after Recovery (Textron)



Photo 4 – View of Angularly Cut Wood at Accident Site



Photo 5 – View of Wreckage Examination Layout (Textron)



Photo 6 – View of Instrument Panel (Textron)



Photo 7 – View of Wing and Flap (AMF Aviation)



Photo 8 – View of Flap Actuator Motor (AMF Aviation)