



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA19FA124



Photo 1 – View of Airplane from Left Side (Photo Courtesy of FBI)



Photo 2 – View of Airplane from Rear (Photo Courtesy of FBI)



Photo 3 – View of Airplane from Right (Photo Courtesy of Lycoming Engine)



Photo 4 – View of Airplane from Front (Photo Courtesy of Lycoming Engine)



Photo 5 – Tree Limbs Evidencing Propeller Strike Marks at Accident Site



Photo 6 – Left Engine Nacelle Fuel Transfer Pump (Photo Courtesy of Piper Aircraft)



Photo 7 – Close-up View of Left Engine Nacelle (Photo Courtesy of Piper Aircraft)



Photo 8 – Right Propeller (Photo Courtesy of Hartzell Propeller)



Photo 9 – Right Propeller Blade 3 (Photo Courtesy of Hartzell Propeller)



Photo 10 – Left Propeller (Photo Courtesy of Hartzell Propeller)