



Photo 1 – NTSB Digital Photograph. View taken Adjacent from Ground Impact Point Looking South. Note the Wreckage in the Background, and Downed Tree Limbs.



Photo 2 - NTSB Digital Photograph. View taken Adjacent from Ground Impact Point Looking Southeast. Note the Wreckage in the Background, and Downed Tree Limbs.



Photo 3 – NTSB Digital Photograph. View taken Adjacent from Ground Impact Point Looking Southeast. Note the Wreckage in the Background.



Photo 4 - NTSB Digital Photograph. View Looking Easterly Direction. Note the Fragmented Wreckage in the Background.



Photo 5 – NTSB Digital Photograph. View Looking in a Southerly Direction. Note the Fragmented Wreckage including Parts of the Wings and Empennage.



Photo 6 – NTSB Digital Photograph. View Depicting the Fractured and Cut Tree Limbs of the Tree Adjacent to the House.



Photo 7 – NTSB Digital Photograph. View Depicting the Separated Empennage.



Photo 8 - NTSB Digital Photograph. View Depicting a Feather Found Adhering to a Blanket Adjacent to the Separated Section of Right Wing.



Photo 9 - NTSB Digital Photograph. View Depicting Left Propeller. Note the Blade Bending.



Photo 10 - NTSB Digital Photograph. View Depicting the right Propeller.



Photo 11 – Piper Digital Photograph. View Depicting the Left Engine.



Photo 12 - NTSB Digital Photograph. View Depicting the Right Engine.