



Photo 1 –Overview of Accident Site (Courtesy of Georgia Bureau of Investigation)



Photo 2 – View of Impact Crater



Photo 3 – View Attitude Indicator Gyro Case



Photo 4 – View of engine



Photo 5 – View of wing section of airplane (foreground is the left wing)



Photo 6 – View of Propeller



Photo 7 – View of disassembled oil filter.



Photo 8 – View of CAPS pin installed in handle. (Courtesy of Cirrus Aircraft)