




Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

ERA19FA250


July 1, 2020



Photograph 1 –Accident site location.



Photograph 2 – Left side view of the accident airplane.



Photograph 3 – Aft right side view of the accident airplane.



Photograph 4 – Aft view of the accident airplane.



Photograph 5 – View of the left wing.



Photograph 6 – View of the left propeller.



Photograph 7 – View of the right propeller.



Photograph 8 – Fuel selector valve positions.



Photograph 9 – Ignition switch (magneto) positions.



Photograph 10 – Removing two sections of the right wing from tree canopy.



Photograph 11 – Section of right wing lodged in tree canopy.