



Photo 1 – Photograph From Owner/Builder. Left Quartering View of the Airplane at the Accident Site.



Photo 2 - Photograph From Owner/Builder. Right Side View of the Airplane Following Recovery.



Photo 3 - Photograph From Owner/Builder. View of the Damaged No. 2 Piston. Note the course Scoring on the Side of the Piston and the Missing Section of Piston Crown.



Photo 4 - Photograph From Owner/Builder. View of the Damaged No. 5 Piston. Note the course Scoring on the Side of the Piston, Missing Section of Piston Crown, and Damaged Piston Ring Lands.



Photo 5 – Photograph From Owner of Similar Airplane With Same Engine. View Depicting Damage to Pistons. Note Damage to the Ring Lands and also Course Scoring on the Sides of the Pistons.