



Memorandum For Record

Timothy W. Monville
Sr. Air Safety Investigator
Eastern Region

Date: April 24, 2020
NTSB Accident Number: ERA19LA032

The airplane builder/owner provided the following information concerning set up of the values in the Engine Control Unit (ECU).

“Before my ground run ups, I obtained numbers from Ron Dalin and Jim Auman. Both were close but not exact so I contacted SDS and got their numbers, which, after [being] adjusted for Mogas I adopted.”