



Photo 1 – View of Airplane with Deployed BRS Parachute in Right Frame (FAA)



Photo 2 – View of Fractured Horizontal Stabilizer Mount (FAA)



Photo 3 View of Fiberglass Delamination and Hole in Empennage Tailcone (FAA)-



Photo 4 – View of Separated Horizontal Stabilizer with Fractured Tailcone Structure Attached (FAA)



Photo 5 – View of Fractured/Separated Tailcone Structure (FAA)