



Photo 1 – Right Side of Fuselage at the Accident Site (Photo Courtesy of FAA)



Photo 2 - Right Side of Fuselage (Photo Courtesy of FAA)



Photo 3 – Puncture of Engine Crankcase at the No. 6 Cylinder, as Viewed at the Accident Site (Photo Courtesy of FAA)