



Photo 1 – Engine



Photo 2 – Fractured Stud, exhaust rocker arm.



Photo 3 – No. 2 cylinder, fractured rocker arm stud.