



Photo 1 – FAA Digital Photograph. View Depicting the Skid Marks in Grass and Airplane in the Background.



Photo 2 - FAA Digital Photograph. Frontal View of the Airplane Where it Came to Rest. Note the collapse Nose Landing Gear.



Photo 3 – Photograph From Pilot. View From Empennage Looking Forward. Note the Collapsed Nose Landing Gear.



Photo 4 - Photograph From Pilot. View of the Upper Portion of the Nose Landing Gear Trunnion Assembly and Steering Horn.



Photo 5 - Photograph From Pilot. View of the Damage to the Lower Portion of the Nose Landing Gear Trunnion Assembly.



Photo 6 - Photograph From Pilot. View of the Engine Mount. Note the sheared bolt that Attached the Nose Landing Gear Actuator.