



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Wreckage Photo Array

ERA19LA097



Photo 1 – Airplane at Accident Scene (Photo Courtesy of FlightSafety)



Photo 2 – Airplane – View from Front (Photo Courtesy of FAA)



Photo 3 – Right Wing Fracture (Photo Courtesy of FAA)



Photo 4 – Stabilator (Photo Courtesy of FAA)



Photo 5 – Left Wing (Photo Courtesy of FAA)



Photo 6 – Left Wing Trailing Edge (Photo Courtesy of FAA)



Photo 7 – Right Wing Outer Leading Edge (Photo Courtesy of FAA)