



RECORD of CONVERSATION

Millicent Hill
Air Safety Investigator
Eastern Region Aviation

Date: August 14, 2019
Person Contacted: Michael Corrigan, FAA Inspector

This investigator interviewed Mr. Thompson by telephone, he stated traveled to the site and examined the helicopter. There was a possible mast bump and the helicopter spun out of control during landing on a training flight. He found damage to the tail boom, isolation mount and the upper cowling around the rotor mast of helicopter.