



Photo 1 – FAA Digital Photograph. View of the Wreckage At the Accident Site.



Photo 2 – NC State Highway Patrol Photograph. Aft Side View of the Left Wing. Note the Impact Damage to the Leading Edge.



Photo 3 - FAA Digital Photograph. Aft Side View of the Right Wing. Note the Fire Damage to the Inboard section of the Wing.



Photo 4 - FAA Digital Photograph. Right Side View of the Upper Portion of The Vertical Stabilizer, Right Stabilizer and Elevator, and Partially Attached Rudder.



Photo 5 - FAA Digital Photograph. View of the Cockpit. Note the Extensive Fire Damage.



Photo 6 – Rotax Digital Photograph. Right Side View of the Engine and Propeller Assembly Following Recovery. Note the Extensive Fire Damage.