



Photo 1 – View of airplane wreckage in tree showing substantial damage to both wings



Photo 2 – View of inside of scat tubing showing the collapsed inner layer



Photo 3 – View of scat tube connector on airframe intake showing crushed fitting