



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA19LA279



Photo 1 – View of Left Wing Trailing Edge and Wingtip Damage (Photo Courtesy of FAA)



Photo 2 – Close-Up View of Wingtip Damage (Photo Courtesy of FAA)



Photo 3 – View of Left Wing Fracture (Photo Courtesy of FAA)



Photo 4 – Left Wing Damage (Photo Courtesy of FAA)