



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Wreckage Photo Array

ERA19TA204



Photo 1 – Submerged Wreckage (Photo Courtesy of FAA)



Photo 2 – Bend in River and Remaining Unmarked Wires (Photo Courtesy of FAA)



Photo 3 – Rear View of Helicopter (Photo Courtesy of FAA)



Photo 4 – Left Side View of Helicopter (Photo Courtesy of FAA)



Photo 5 – Separated Tail Boom (Photo Courtesy of FAA)



Photo 6 – Right Side View of Helicopter (Photo Courtesy of FAA)



Photo 7 – Telephone Wire Wrapped Around Main Rotor (Photo Courtesy of FAA)



Photo 8 – Close-up of Telephone Wire Around Main Rotor (Photo Courtesy of FAA)