



Photo 1 – Forward view of damaged right landing gear. (Courtesy of FAA)



Photo 2 – Damaged right landing gear. (Courtesy of FAA)



Photo 3 – Top of right wing buckling. (Courtesy of DCAVIATION)



Photo 4 – Right wing looking aft. Note buckling on rivet line. (Courtesy of DCAVIATION)



Photo 5 – View of fuel vent that was blocked with debris. (Courtesy of DCAVIATION)