



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20CA048



Photo 1 – View of Airplane from Right Side (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Front (Photo Courtesy of FAA)



Photo 3 – Delamination of Wing Spar (Photo Courtesy of FAA)



Photo 4 – Delamination of Wing Spar (Photo Courtesy of FAA)