

Photo Array for ERA20LA103

Photographs provided by the Federal Aviation Administration



Photograph 1 - Accident airplane right main gear sheared torque link bolt.

Photo Array for ERA20LA103

Photographs provided by the Federal Aviation Administration



Photograph 2 - Accident airplane left main gear.



Photograph 3 - Accident airplane left wing damage.