



## Investigative Photographs

Peter Wentz  
Air Safety Investigator  
Eastern Region Aviation

ERA20FA012

October 26, 2020



**Photograph 1 –Accident site.**



**Photograph 2 – Left side view of the accident helicopter.**



**Photograph 3 – Under side view of the accident helicopter.**



**Photograph 4 – Forward nose section of the accident helicopter.**



**Photograph 5 – Aft view of the accident helicopter.**



**Photograph 6 – Main rotor shaft.**



**Photograph 7 – Tail rotor.**



Photograph 8 – Fuel/chemical truck.



Photograph 9 – Top of vertical stabilizer.



Photograph 10 – Detached rotor blade.



Photograph 11 – Helicopter instrument panel.