



Photo 1 – Photograph Provided by Martin County Sheriff Department. Aerial View of the Accident Site. Note the Wreckage Debris.



Photo 2 - NTSB Digital Photograph. View of the Initial Impact Site. Note the Wreckage.



Photo 3 - NTSB Digital Photograph. View of One Propeller Blade of the Left Propeller and Left Engine on Initial Impact Site. Also note, nearby wreckage.



Photo 4 - NTSB Digital Photograph. View of the Initial Impact Site. Note the Majority of Wreckage in the Background.



Photo 5 - NTSB Digital Photograph. View of The Wreckage on and Nearby the Initial Impact Site.



Photo 7 - NTSB Digital Photograph. View of The Wreckage at the Accident Site.



Photo 8 - NTSB Digital Photograph. View of The Wreckage at the Accident Site. Note the cockpit in the Background.



Photo 9 - NTSB Digital Photograph. View of A Portion of the Left Wing.



Photo 10 - NTSB Digital Photograph. View of the Reconstruction of the Right Wing.



Photo 11 - NTSB Digital Photograph. View Showing the Static Imprint of the Inboard End of the Left Elevator Against the Adjacent Aft Empennage Skin.



Photo 12 - NTSB Digital Photograph. Annotated Photograph Showing each Engine, Propeller, and Separated Propeller Blades.