



**Photo 1 – Wide angle view of airplane wreckage looking towards the initial impact site about 180 ft in the background.
(Courtesy of Coweta County Police)**



Photo 2 – Close up view of fuselage damage looking towards the initial impact site that originated about 180 ft in the background.



Photo 3 – Wide view of left side of airplane wreckage and debris field.



Photo 4 – Aft view of wreckage.



Photo 5 – Wreckage path and direction of travel. Note airplane debris and broken limbs.



Photo 6 – Close up view of left side of empennage (inverted) showing damage to horizontal and vertical stabilizer.



Photo 7 – View of separated propeller after removal from the ground.



Photo 8 – View of underside of the engine as discovered at the accident site.



Photo 9 – View of separated left wing as discovered at the accident site; about 20 feet from the main wreckage.



Photo 10 – View of right wing damage as it lays over top of the fuselage.



Photo 11 – View of top side of engine after recovery.



Photo 12 – View of left and right muffler assemblies after recovery from site.