



Photo 1 – NTSB Digital Photograph. View of the Helicopter Fuselage at the Accident Site.



Photo 2 - NTSB Digital Photograph. View of the Separated Main Rotor Mast with Attached Main Rotor Blades.



Photo 3 - NTSB Digital Photograph. Different View of the Separated Main Rotor Mast with Attached Main Rotor Blades.



Photo 4 - NTSB Digital Photograph. View of the Location Where the Main Rotor Mast with Attached Blades was Found Before Being Moved.



Photo 5 - NTSB Digital Photograph. View of the Separated Tail Rotor Assembly. Note the fractured Tail Rotor Blade.



Photo 6 - NTSB Digital Photograph. Close-Up View of the fractured Tail Rotor Blade Showing the recovered Section of Tail Rotor Blade in the Photograph.



Photo 7 - NTSB Digital Photograph. View of a Portion of the Separated Tailboom.




Photo 8 - NTSB Digital Photograph. View of the Separated Portion of Main Rotor Blade and Corresponding Location.



Photo 9 – FAA Digital Photograph. View of the Inboard Section of the Separated Main Rotor Blade. Note the Feather Adhering to the Upper Surface of the Blade near the Leading Edge.