



Investigative Photographs

ERA20LA054

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

Photographs provided by Alamo Helicopters



Photograph 1 – Accident helicopter – front view.



Photograph 2 – Accident helicopter – underside view.



Photograph 3 – Accident helicopter – photo of front seat.



Photograph 4 – Accident helicopter – tail rotor.



Photograph 5 – Accident helicopter – tail boom.



Photograph 6 – Accident helicopter recovered to flatbed.