




**Photo 1 – View of right side tail damage. Right stabilizer missing. Right elevator bent down and damaged. (Courtesy of Owner)**



**Photo 2 – Close up view of right elevator damage. Note the stabilizer is missing and entire structure is bent down.  
(Courtesy of Owner)**




**Photo 3 – View of empennage looking forward. Both left and right sides bent down. Right side missing stabilizer.  
(Courtesy of Owner)**



**Photo 4 – View of right horizontal stabilizer failed aft spar and flange. (Courtesy of Owner)**



**Photo 5 – Photo of forward spar inboard attachment straps/rivets. Note they are bent down and aft. (Courtesy of Owner)**



**Photo 6 – Closeup of forward spar attachment straps missing rivets inboard. (Courtesy of Paul Romano)**